08634

ZPrinter®310 Troubleshooting Guide

Rev B



Revision History:

Rev 06:	JPK	1/6/2003	Unreleased revision
Rev A:	JPK	2/24/2003	Released
Rev B:	BRS	8/12/04	Revised ECN 1323

Z, zp, zb, ZPrinter, ZCast and the Z Corp. logo are trademarks of Z Corporation.

Information contained in this document is the confidential property of Z Corporation. Recipient shall not disclose such Information to any third party, and shall not use it for any purpose whatsoever other than to price or provide services to Z Corporation.

© Z Corporation 1995-2002. All rights reserved.

SYMPTOM	CAUSE / PROBLEM	LIKELIHOOD + HIGH - LOW	SOLUTION
	Print head failure	+	Replace print head
	Binder bottle not plugged into top cover	+	Check connection to binder bottle
	Out of binder	+	Refill binder bottle and bleed fluid system (see users manual chapter 6)
	Air in fluid system	_	Bleed fluid system (see users manual chapter 6)
	Binder tubing blocked or kinked	-	Check for kinks and replace tubing if necessary (see 08632 Benchwork manual)
Error 1006 Message	Binder valve at head card not connected or loose	-	Check valve connection
(Head Temp too high)	Poorly seated carriage flex cable	_	Check carriage flex cable connections
	Bad carriage cable (open circuit)	-	Check carriage flex cable integrity, replace if necessary
	Bad head card	_	Replace head card
	Binder cap vent clogged	_	Check cap vent for blockage
	Pogo pin / pins are bent or broken	-	Change pogo card (See 08632 Benchwork manu
	Fluid filter clogged		Replace or clean fluid filter (See 08632 Benchwork manual)
	Organisms growing in binder	-	Flush fluid system with bleach solution, change binder
Error 1000 Message (Unknown head error)	No print head installed	+	Install and purge new print head (see users manual chapter 12)
	Tape still in place over print head contacts	+	Remove tape and re-install pen
	Carriage cable damaged / not seated in connector	-	Check cable and connector
	Pogo pin / pins are bent or broken	-	Change pogo card (See 08632 Benchwork manu
	Bad carriage cable (open circuit)	-	Check carriage flex cable integrity, replace if necessary
	Bad head card	-	Replace head card (See 08632 Benchwork manual)

Error 1002 Message (Rom read failed for head)	Print head not seated correctly	+	Re-seat pen and restart build
	Pogo pin / pins are bent or broken	-	Change pogo card (See 08632 Benchwork manual)
	Head card ribbon cable disconnected at either end	-	Check head card ribbon cable connections
	Tape still in place over print head contacts	-	Remove tape and re-install pen
Error 1003 Message	Print head failure, bad smart chip	-	Print head failure, bad smart chip
(I2C read failed for head)	Pogo card malfunction	+	Inspect pogo cards. Pins should be clean and not bent or broken
	Flash card not connected to ATX power supply	+	Check power connection to flash card
	Bad PCI card	+	Replace PCI Card (See 08632 Benchwork manual)
Machine will not boot or	Flash card corrupt or erased	-	Replace flash card or check master slave switch
come online	Dead CMOS battery on motherboard	-	Change CMOS battery. (See 08632 Benchwork manual)
(Power LED is on)	Voltage selector set wrong on power supply (selector set to 230V with 110V input)	-	Unplug printer and set selector to proper voltage
	PCI Card not seated properly	-	Check PCI to motherboard connection
	PCI EEPROM chip not seated or bad	-	Re-seat or replace EPROM chip
Online / Error lights flash and long sustained beep	Interlock switch not connected to Igus harness properly or malfunctioning interlock switch	+	Check connection to switch or replace switch (See 08632 Benchwork manual)
	Bad PCI card	-	Replace PCI Card (See 08632 Benchwork manual)
Binder dripping onto top deck	Septum / barb fitting leaking or binder tubing not properly inserted onto barb fitting at print head	+	Replace septum if necessary. Check tubing connection at barb fitting
Error 2303(0) message (Axis excessive position error)	Power cable not connected to middle connector on the PCI card	+	Check connection at PCI card.
	Slow Axis bearings low on grease or seized	+	Grease slow axis bearings or replace slow axis bearings if necessary.
	Slow Axis cable disconnected or forced on backward	-	Check slow axis cable connection
	Slow Axis motor failure	-	Replace slow axis motor. (See 08632 Benchwork manual)
	Slow Axis idler pulley seized	-	Change Slow Axis idler (See 08632 Benchwork manual)

Error 2303(1) message (Axis excessive position error)	Low on Fast Axis oil	+	Oil Fast Axis felt washers (see users manual)
	Fast Axis motor cable not properly connected at the head card	+	Check Fast Axis plug connection
	Debris in Fast Axis bearings	+	Inspect Fast Axis Bearings and clean or replace if necessary
	Fast Axis belt too tight	+	Adjust belt to proper tension (See 08632 Benchwork manual)
	Fast Axis bearing seize	-	Replace Fast Axis bearings
	Fast Axis tensioner seized	-	Replace tensioner
	Fast Axis motor failure	-	Replace fast Axis motor
	Fast axis anti-rotate bearing missing	-	Replace Anti-rotate bearing
Printing stripes	Print head failing	+	Replace print head
	Pogo Pins contaminated or dirty	+	Clean Pogo Pins with alcohol swab
	Service Station out of cleaning fluid	-	Fill cleaning fluid reservoir
	Powder build – up on service station cap	-	Clean service station cap
"Packet Timeout" message	Bad serial port on PC or printer	+	Replace motherboard
	AC cord to printer not plugged in	+	Plug in printer AC cord
7. 4	Power switch failure	-	Check switch, test and replace if necessary
Printer will not turn on	Power supply failure	-	Change power supply
(won't power up)	Power supply shorted	-	Unplug AC cord, wait 10 seconds, reconnect AC cord and reboot printer
	Voltage selector set wrong on power supply (selector set to 110V with 230V input)	-	Replace power supply
Control panel won't respond to inputs	Control panel switches malfunctioning	+	Replace control panel (See 08632 Benchwork manual)
	Bad PCI Card	-	Replace PCI Card (See 08632 Benchwork manual)
	Bad control panel cable	•	Replace control panel cable (See 08632 Benchwork manual)
	Control Panel cable not properly connected	-	Check control panel cable connections

Service Station Overflowing	Waste bottle not installed / halfway installed to valve at front panel	+	Check connection at waste bottle mount
	Waste tube clogged	•	Unclog or replace waste tube
	Waste bottle vent clogged	-	Check and unclog cap vent or replace cap
	Waste Bottle not plugged in properly	+	Check connection of Waste Bottle to check valve
"Before printing you must fix this problem" Message	Main harness disconnected at PCI card.	+	Check main harness connection at PCI card
Binder leaking from back of machine	Binder filter leaking	+	Check filter o-ring and filter body for proper assembly
Build piston is stuck and	Wet piston seal has dried against build box wall	+	Replace piston seal (see 08632 Benchwork manual)
or will not move through its full range of travel	Debris jamming the piston	•	Check for any debris and remove; clean the build box walls if ant buildup has occurred
its full range of traver	Energizer jamming the piston	•	Replace energizer and seal (see 08632 Benchwork manual)
	Faulty PCI card	•	Replace PCI card (see 08632 Benchwork manual)
Build piston will not come all the way to the top of the build box	Piston positions incorrect. Pistons not re-zeroed after PCI / E Box replacement.	+	Re-zero pistons
Excessive overspread into service station / gantry jams	Feed piston raised too far before spreading	+	Clean away excess powder, clean print head and reboot printer
Uneven or rough spreading	Powder is contaminated or over-recycled	+	Discard old powder and fill feed box with fresh powder
	Roller scraper worn	-	Replace roller scraper (See 08632 Benchwork manual)
	Binder/powder caked on roller	-	Check scraper for wear or clean roller
	Spreader roller motor failing	-	Replace spreader roller motor (See 08632 Benchwork manual)
	Roller belt skipping teeth		See 09813 Service bulletin for instructions

Parts weak, crumbly, wet or caked with powder	Print head failing	+	Replace print head
	Incorrect saturation setting	+	Set correct saturation for powder /binder system being used
	Wrong binder being used	+	Replace binder with correct formula
	User recycled binder	-	Replace binder with correct formula
	Powder is contaminated or over-recycled	-	Discard old powder and fill feed box with fresh powder
Excessive powder on top deck	Snowplows not attached or severely worn	+	Attach snowplows correctly or replace
Error light when booting	Head card PLD not programmed	+	Program head card PLD
Error nguv when sooting	Carriage ribbon cable not connected at either end	-	Check for proper ribbon cable connection
Squeaking noise from inside cabinet while raising or lowering the pistons	Lead screws running without lubricant	+	Grease lead screws
Slow axis belt skipping	Slow axis belt too loose	+	Tighten Slow Axis belt to proper tension
teeth / chattering	Slow Axis idler pulley seized	-	Replace slow axis idler (See 08632 Benchwork manual)
	Slow Axis zeroed in wrong location	+	Re-boot printer
Gantry slams and carriage is not parked at service station after booting	Slow axis motor encoder malfunctioning or wired improperly	-	Replace or re-wire slow axis motor encoder (See 08632 Benchwork manual)
	Bad head card	-	Replace head card (See 08632 Benchwork manual)
	Fast Axis zeroed in wrong location	+	Re-boot printer
Carriage slams and will not park at service station after booting	Fast axis motor encoder malfunctioning, wired improperly or disconnected from head card	-	Replace, reconnect or re-wire fast axis motor encoder (See 08632 Benchwork manual)
	Bad PCI Card	-	Replace PCI Card (See 08632 Benchwork manual)

Fast axis belt skipping teeth / chattering	Fast axis belt too loose		Tighten Fast Axis belt to proper tension
Can't find printer on network	Poor Ethernet connection or improper setup	+	See 08606 Ethernet setup procedure for instructions
	Service Station out of cleaning fluid	+	Fill cleaning fluid reservoir
	Powder build – up on service station cap	+	Clean service station cap
	Pogo Pins contaminated or dirty	-	Clean Pogo Pins with alcohol swab
	Print head not seated correctly	-	Re-seat pen and restart build
Short Print Head Life	Pogo pin / pins are bent or broken	-	Change pogo card (See 08632 Benchwork manual)
	Concentration of color binder too high	-	Bleed fluid system and verify correct color binder concentration before restarting
	Air bubbles in fluid system	-	Bleed fluid system (see users manual chapter 6)
	Contaminated binder	-	Flush fluid system with bleach solution, change binder
Error 30004 message	Igus Ribbon cable disconnected at either end	+	Check Igus ribbon cable for proper connection